

AL 3546830

# TUNING VARACTOR

$C_0$  =      ODS     

$C_{47}$  = 4.03

$C_{48}$  = 2.19

$C_{45}$  =      CRI 1.84

$C_{55}$  =     

$C_{60}$  =     

$C_{90}$  =     

Q = 143

$R_s$   $\bullet$       MA =     

$\phi$  =      °C/wt

$I_R$   $\bullet$  40.5 V = 3.0 NA

$V_B$  = 49

Diff. No. 3649